

Product Name: Glass Lite

Description: Autotriz Glass Lite creates a thin film layer repelling water and dirt from glass. This unique formulation has excellent chemical resistance. Its super hydrophobic properties allow rain flowing off glass surface, resulting in increase of visibility especially in rain and snow. It acts as an exceptional water-repellent coating that reduces water spots on glass. Enhanced clarity of glass makes your driving experience safer and more comfortable.



Coverage: Glass Lite Coating is particularly suitable for all glass surfaces and recommended for side windows.

Technical Data		General Data	
Shelf life	12 months	Product	Glass Lite
Appearance	Colorless	Category	Automotive Coating
Curing	Normal ambient	Volume	50ML (AT-V5L-50)
Base	Advance Silicon	Application	Vehicle Windows
Specified Gravity	0.76 g/cm ³	Coverage	50ML (10m ² - 12m ²)
Hazard	Non-Hazardous	Storage	5-35°C/41-95°F
Properties		Tools Needed	
<ul style="list-style-type: none"> • Super hydrophobic • Reduce glare • Cures instantly • Easy-to-clean • Excellence adhesion • Excellent chemical resistance • Improve visibility in rain • Increase safety 		<ul style="list-style-type: none"> • Applicator block (AT-AC-AB) • Microfiber Suede cloth (AT-AC-MS) • Lint-free microfiber towel (AT-AC-MC) 	

Guide: The product is for professional use and should be applied by approved applicators only. Test on a small area or apply a test coat before application.

Instruction: Buff the glass surfaces thoroughly with AUTOTRIZ Glass Cut Compound to remove any contaminants or water spots. Wrap the applicator sponge with the white microfiber suede cloth that comes with the box or use applicator of your preference. Tack cloth or paper towel is also recommended. Apply Glass Lite Coating in medium pressure on entire side windows and rear windscreen where no wiper is attached. Apply product by working in horizontal, or vertical movements in fast motion to ensure that product is carried through evenly. The hint to applying Glass Lite Coating is to form an even and smooth coating film on the glass surface. Glass Lite Coating can be wiped off immediately using clean microfiber towels until all film or haze is removed. It can also be washed off immediately using water or shampoo to inspect its hydrophobic effects and to make sure the coating is applied correctly without leaving any uneven spots or stripes. If the results are not satisfactory, reapply Glass Lite Coating on the whole piece of window glass to form a new layer of coating.

Precaution: Ensure the substrate is free from contaminants prior to and during the application process. Keep coating away from all polish and compound dust during the curing process.

Process and Curing: The product must be applied at an ambient temperature of at least + 5°C and relative humidity of 30 % - 80 %. Avoid direct sunlight! Apply the coating in clean and dry conditions. Any mistakes can be rectified within approx. 10 min of application. Traces of water in the applicator should also be avoided. Applicators dampened with water should not be used. The applicators cannot be reused once the coating has been applied.